COMMON LOCATIONS OF ASBESTOS IN INDUSTRIAL BUILDINGS



- Asbestos cement water tanks
- Lagging around pipes and boilers
- 3 Vinyl floor tiles
- Toilet seats and cisterns
- 5 Cladding and roofing
- Gutters and downpipes

- Textured coatings on walls and ceilings
- 8 AIB partition walls
- 9 Ceiling tiles
- AIB panels in fire doors
- 11 Insulation
- 12 In the ground

Note: These are common locations of asbestos however the list is not exhaustive.